To return the Year Code from a factory defective liner for credit, cut out the area indicated by the oval dotted line and a similar cut out of the defective area and return to the Customer Service Warranty Department. Liners no longer have the "Logo" printed on them. All liners will now have just the item number and the year code on them. It is still located at the same area as before. This area must be sent in along with any defective area for credit.

Cut out this
Approximate
Area

Liner
Side
Wall

Liner Side Wall

This is the ground
Side of the liner

Year Code

0 –0000-000-000-"Y"

Location of the liner code number

You must cut out two
Inches beyond seams

SWATCH

Bottom seam

Liner bottom